

## **Optional Accessories**

Fluke power quality current transformers and fl exible current probes are specially designed to work seamlessly with Fluke power monitors (1750 and 1650). All clamp-on and fl exi-CT's are matched to take full advantage of your instrument's ability to set scale factors for accurate readings.





Model No.	CT Type C	urrent Range Acc	uracy	Frequency Response	law Opening
3005-PR	Clamp-On (	).01 A to 5 A 1	% RDG ± 0.5 % FS 5 kH	z 2 cm	(.78 in) dia.
3014-PR	Clamp-On (	).1 A to 40 A 1	% RDG ± 0.1 % FS 5 kH	z 2 cm	(.78 in) dia.
3140R	Clamp-On	2 A to 400 A 2	% RDG ± 0.04 A 20 k	Hz 3.2 c	m (1.25 in) dia.

